



GM Recalls 300,000 Impalas Due To Seat Belt Problem

Written On October 19, 2010 By [Bob Kraft](#)

General Motors has announced the recall of more than 300,000 Chevrolet Impala sedans because the front seat belts may fail to restrain people in a collision.

The National Highway Traffic Safety Administration says the front-seat belt webbing may not be secured properly to a lap belt anchor on the side of the seat near the doors.

The recall affects 2009 and 2010 Impalas. Owners will be notified later this month and can contact Chevrolet at 1-800-630-2438. If you receive a recall notice your dealer will inspect the seat belts and repair them at no cost.

Kraft & Associates
2777 Stemmons Freeway
Suite 1300
Dallas, Texas 75207
Toll Free: (800) 989-9999
FAX: (214) 637-2118
E-mail: info@kraftlaw.com