CHILD SAFETY BLOG

PATRICK MALONE & ASSOCIATES, P.C. From Tragedy To Justice - Attorneys For The Injured Toll Free: 888.625.6635 (888.MaloneLaw) Local: 202.742.1500



Posted On: November 18, 2010 by Patrick A. Malone

Big recall of Roman shades, roll-up blinds and roller blinds because of strangling hazard in small kids

In conjunction with the U.S. Consumer Product Safety Commission (CPSC), Hanover Direct Inc. (also known as Domestications, The Company Store and Company Kids) has recalled nearly 500,000 Roman shades, roll-up blinds and roller blinds because of strangulation hazards to small children.

In October 2009, about 90,000 Roman shades were recalled due to strangulation fears. Strangulations can occur when a child places his/her neck between the exposed

Patrick A. Malone Patrick Malone & Associates, P.C. 1331 H Street N.W. Suite 902 Washington, DC 20005 pmalone@patrickmalonelaw.com www.patrickmalonelaw.com 202-742-1500 202-742-1515 (fax)

Copyright 2010 Patrick Malone

inner cord and the fabric on the backside of the blind or when a child pulls the cord out and wraps it around his/her neck.

The latest recall of about 495,000 items came after a 22-month old boy was found hanging from his neck from the outer cords of a Roman shade in May. The outer pull cords were knotted at the bottom. The child was rescued by his father but later died in a hospital.

To date, no injuries or incidents attributable to rollup or roller blinds have been reported. However, strangulations can occur with roll-up blinds if the lifting loops slide off the side of the blind and a child's neck becomes entangled on the free-standing loop or if a child places his/her neck between the lifting loop and the roll-up blind material. With roller blinds, strangulations can occur if the blind's continuous loop bead chain or continuous loop pull cord is not attached to the wall or the floor with the tension device provided and a child's neck becomes entangled in the free-standing loop.

The new recall involves all styles of Roman shades with inner cords, all styles of roll-up blinds, and roller blinds that do not have a tension device. A tension device is intended to be attached to the continuous loop bead chain or continuous loop pull cord and installed into the wall or floor.

The blinds were sold at Hanover Direct/Domestications, the Company Store/Company Kids; online at www.domestications.com and www.thecompanystore.com; and through catalog sales nationwide from January 1996 through October 2009 for between \$20 and \$579. They were manufactured in China, the United States, and other countries.

Patrick A. Malone Patrick Malone & Associates, P.C. 1331 H Street N.W. Suite 902 Washington, DC 20005 pmalone@patrickmalonelaw.com www.patrickmalonelaw.com 202-742-1500 202-742-1515 (fax)

Copyright 2010 Patrick Malone

Consumers should immediately stop using all Roman shades with inner cords, all rollup blinds, and all roller blinds that do not have a tension device, and contact the Window Covering Safety Council at (800) 506-4636 anytime for free repair kits or visit www.windowcoverings.org.

Consumers who have roller blinds with a tension device should make sure the tension device is attached to the continuous loop bead chain or continuous loop pull cord and is installed into the wall or floor.

Source: Babyzone.com

You can view the original CPSC recall report here.

Families interested in learning more about our firm's legal services, including legal representation for children who have suffered serious injuries in Washington, D.C., Maryland and Virginia due to medical malpractice, defective products, birth-related trauma or other injuries, may ask questions or send us information about a particular case by phone or email. There is no charge for contacting us regarding your inquiry. An attorney will respond within 24 hours.

All contents copyrighted 2010 <u>Patrick Malone & Associates</u> except where copyright held by others. Reproduction in any form prohibited except where expressly granted.

Patrick A. Malone Patrick Malone & Associates, P.C. 1331 H Street N.W. Suite 902 Washington, DC 20005 pmalone@patrickmalonelaw.com www.patrickmalonelaw.com 202-742-1500 202-742-1515 (fax)

Copyright 2010 Patrick Malone